




**NOTE: Parts are no longer available for this tool.**

**The manual will continue on the next page.**



# PARTS LIST FOR 500A (SPINDLE ADAPTER)

- 1. 65881 Adapter-Spindle
- 2. 65497 Washer (2)
- 3. 09622 Nut



# SIoux TOOLS INC.

250 SNAP-ON DRIVE ■ PO BOX 1596 ■ MURPHY, NC 28906 ■ USA ■

Printed in U.S.A.

This pdf incorporates the following model numbers:

500A