



PARTS LIST FOR 45° ANGLE HEAD ASSEMBLY




FIG. NO.	PART NO.	NAME
1.	65238	Bushing—Flange
2.	65246	Pin (2)(Set of 22)
3.	65236	Gear—Collet (1/4–28 Th'd)
	65264	Gear—Collet (#10–32 Th'd)
	65538	Gear—Collet (9/32"–40 Th'd)
4.	30375	Fitting—Grease
5.	65237	Housing—45°
6.	65235	Pinion
7.	65245	Retainer—Bearing
8.	65240	Shim—.003"
	65241	Shim—.004"
	65242	Shim—.005"
		Order Quantity As Needed
9.	65244	Housing—Angle Drill
10.	10257	Bearing—Ball
11.	65243	Nut—Retaining
12.	65143	Nut—Jam
13.	65146	Adaptor—Spindle
14.	44122	Spacer
	65213	Assembly—Complete (1/4"–28 Th'd) (Includes Figs. 1–11)
	65265	Assembly—Complete (#10–32 Th'd) (Includes Figs. 1–11)
	65541	Assembly—Complete (9/32"–40 Th'd) (Includes Figs. 1–11)

**SIoux
TOOLS INC.**