



NOTE: Parts are no longer available for this tool.

The manual will continue on the next page.

SIoux**TOOLS**

Parts List for No. 617B Dressing Attachment




Fig- ure	Part No.	Name	Fig- ure	Part No.	Name
1	14092	Ball—Grip	10	24646	Bolt
2	53080	Handle	11	25372	Washer
3	10430	Bushing	12	30456	Seal—Oil (2)
4	08104	Screw—Handle	13	11165	Base
5	54080	Pin—Swivel	14	21280	Spring—Diamond Tension
6	54079	Bar—Slide	15	13092	Slug—Brass
7	43019	Casting—Slide (Includes Fig. 12)	16	1715	Diamond—Dressing
8	09950	Screw—Drive (2)		99	Wheel—Grinding
9	20402	Plate—Name			

SIoux TOOLS INC.
 SIoux CITY, IOWA, U.S.A. 51102

SIoux



TOOLS

Parts List for No. 617 Dressing Attachment




Fig- Part
ure No.

Name

- | | | |
|---|-------|-----------------|
| 1 | 23435 | Handle |
| 2 | 24651 | Screw—Handle |
| 3 | 24650 | Pin—Swivel |
| 4 | 24647 | Bar—Slide |
| 5 | 43019 | Casting—Slide |
| 6 | 09950 | Screw—Drive (2) |
| 7 | 20068 | Plate—Name |
| 8 | 24646 | Bolt |

Fig- Part
ure No.

Name

- | | | |
|----|-------|------------------------|
| 9 | 25372 | Washer |
| 10 | 23437 | Oil Seal, Complete (2) |
| 11 | 11165 | Base |
| 12 | 21280 | Spring—Diamond Tension |
| 13 | 13092 | Plug—Brass |
| 14 | 1715 | Diamond—Dressing |
| | 99 | Wheel—Grinding |

SIoux TOOLS INC.
SIoux CITY, IOWA, U.S.A. 51102

PRINTED
IN
U.S.A.

This pdf incorporates the following model numbers:

617B